FILE NO: 728

This document gives pertinent information concerning the VPDES Permit listed below. This permit is being processed as a MAJOR, INDUSTRIAL permit.

1. PERMIT NO: VA004103

NO.: VAU04103	EXPIRATION DATE: August 15, 2012
	·
TY NAME AND LOCAL MAILING	FACILITY LOCATION ADDRESS (IF DIFFERENT)
The state of the s	
vn, VA 23692	
	CONTACT AT LOCATION ADDRESS
	NAME: Laura A. Shumaker
	TITLE: Environmental Compliance Coordinator
	- 4
	PHONE: (757)898-2555
Cathy.C.Tayloredom.com	EMAIL: Laura.A.Shumaker@dom.com
TO DECEMBE	CONCIL BAND COMBACIL.
	CONSULTANT CONTACT: NAME:
	FIRM NAME:
	FIRM NAME.
	ADDRESS:
<del></del>	<u>ADDRIGO</u> .
_	
	PHONE: ( )
(004)273 2323	EMAIL:
	· .
DRAFTED BY: DEO, Water Permi	its, Regional Office
Writer(s): Melinda Woodruff	Date(s): April 6, 2012 - May 22, 2012
	Date(s): April 6, 2012 - May 22, 2012  Date(s): 5/73-24/12, 6/1/12
- Joines (Doc)	, , , , , , , , , , , , , , , , , , , ,
ACTION:	
	D. J. & D. J. L
uance (x) Reissuance ()	Revoke & Reissue ( ) Owner Modification
rd Modification ( ) Change	of ownership/name [Effective pare: ]
	•
	•
	TY NAME AND LOCAL MAILING on - Yorktown Power Station aterview Road on, VA 23692  PAT FACILITY: Cathy C. Taylor Director Electric mental Services (804)273-2929 Cathy.C.Taylor@dom.com  CONTACT: (TO RECEIVE PERMIT) C.D. Holley V.P. Fossil & Hydro Systems ions (NAME: (IF DIFFERENT) S: 5000 Dominion Blvd. Allen, VA 23060 (804)273-2929  DRAFTED BY: DEQ, Water Permit Writer(s): Melinda Woodruff

### SUMMARY OF SPECIFIC ATTACHMENTS LABELED AS:

Attachment 1 Attachment 2 Attachment 3 Attachment 4 Attachment 5 Attachment 6	Site Inspection Report/Memorandum Discharge Location/Topographic Map Schematic/Plans & Specs/Site Map/Water Balance TABLE I - Discharge/Outfall Description TABLE II - Effluent Monitoring/Limitations Effluent Limitations/Monitoring Rationale/Suitable Data/Antidegradation/Antibacksliding
Attachment 7 Attachment 8 Attachment 9 Attachment 10	Special Conditions Rationale Toxics Monitoring/Toxics Reduction/WET Limit Rationale Material Stored Receiving Waters Info./Tier Determination/STORET Data/Stream Modeling/303(d) Listed Segments
Attachment 11 Attachment 12 Attachment 13 Attachment 14	TABLE III(a) and TABLE III(b) - Change Sheets NPDES Industrial Permit Rating Worksheet and EPA Permit Checklist Chronology Sheet Public Participation

APPLICATION COMPLETE: March 12, 2012

PERMIT CHARACTERIZATION: (Check a	as many as appropriate)
<pre>(x) Existing Discharge ( ) Proposed Discharge ( ) Municipal     SIC Code(s) (x) Industrial     SIC Code(s) 4911 ( ) POTW ( ) PVOTW (x) Private ( ) Federal</pre>	(x) Effluent Limited (x) Water Quality Limited () WET Limit () Interim Limits in Permit () Interim Limits in Other Document () Compliance Schedule Required () Site Specific WQ Criteria () Variance to WQ Standards () Water Effects Ratio (x) Discharge to 303(d) Listed Segment (x) Toxics Management Program Required
( ) State ( ) Publicly-Owned Industrial	( ) Toxics Reduction Evaluation (x) Storm Water Management Plan ( ) Pretreatment Program Required ( ) Possible Interstate Effect ( ) CBP Significant Dischargers List

### 8. RECEIVING WATERS CLASSIFICATION: River basin information.

Outfall No(s): 001, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 002, 202, 203, 204, 205, 005, 006, 007, 008, 011, 014, 015, 016

Receiving Stream: York River

River Mile: see attachment 10

Basin: York River

Subbasin: NA Section: 1 Class: II

Special Standard(s): a, NEW-17

Tidal: YES
7-Day/10-Year Low Flow: NA
1-Day/10-Year Low Flow: NA
30-Day/5-Year Low Flow: NA

Outfall No(s): 009 and 010

Receiving Stream: Unnamed Tributary to the York River

River Mile: see attachment 10

Basin: York River

Subbasin: NA
Section: 1
Class: II

Special Standard(s): a, NEW-17

Tidal: YES
7-Day/10-Year Low Flow: NA
1-Day/10-Year Low Flow: NA
30-Day/5-Year Low Flow: NA
Harmonic Mean Flow: NA

Outfall No(s): 003, 004 and 017

Receiving Stream: Unnamed Tributary to Chisman Creek

River Mile: see attachment 10

Basin: Chesapeake Bay, Atlantic Ocean and Small Coastal

Subbasin: NA
Section: 2d
Class: III
Special Standard(s): None
Tidal: YES
7-Day/10-Year Low Flow: NA
1-Day/10-Year Low Flow: NA
30-Day/5-Year Low Flow: NA
Harmonic Mean Flow: NA

Outfall No(s): 012 and 013

Receiving Stream: Unnamed Tributary to Wormley Creek

River Mile: see attachment 10

Basin: York River

Subbasin: NA
Section: 1
Class: II

Special Standard(s): a,NEW-17

Tidal: YES
7-Day/10-Year Low Flow: NA
1-Day/10-Year Low Flow: NA
30-Day/5-Year Low Flow: NA
Harmonic Mean Flow: NA

9.	FACILITY DESCRIPTION: Describe the type facility from which the discharges originate.
	Existing industrial discharge resulting from the generation of electricity with steam produced by the combustion of fossil fuels.
10.	<u>LICENSED OPERATOR REQUIREMENTS</u> : ( ) No (x) Yes Class: III
11.	RELIABILITY CLASS: Industrial Facility - NA
12.	SITE INSPECTION DATE: August 27, 2009 REPORT DATE: September 2, 2009
	Performed By: Clyde Gantt
	SEE ATTACHMENT 1
13.	DISCHARGE(S) LOCATION DESCRIPTION: Provide USGS Topo which indicates the discharge location, significant (large) discharger(s) to the receiving stream, water intakes, and other items of interest.
	Name of Topo: Poquoson West Quadrant No.: 65B SEE ATTACHMENT 2
14.	ATTACH A SCHEMATIC OF THE WASTEWATER TREATMENT SYSTEM(S) [IND. & MUN.]. FOR INDUSTRIAL FACILITIES, PROVIDE A GENERAL DESCRIPTION OF THE PRODUCTION CYCLE(S) AND ACTIVITIES. FOR MUNICIPAL FACILITIES, PROVIDE A GENERAL DESCRIPTION OF THE TREATMENT PROVIDED.
	SEE ATTACHMENT 3 (CAN ALSO REFERENCE TABLE I)
15.	DISCHARGE DESCRIPTION: Describe each discharge originating from this facility.
	SEE TABLE I (OR CAN SUBSTITUTE PAGE 2C) - SEE ATTACHMENT 4
16.	COMBINED TOTAL FLOW:
	TOTAL: 963.7 MGD (for public notice)
	PROCESS FLOW: 962 MGD (IND.)
	NONPROCESS/RAÏNFALL DEPENDENT FLOW: 1.7 (Est.)
17.	STATUTORY OR REGULATORY BASIS FOR EFFLUENT LIMITATIONS AND SPECIAL CONDITIONS: (Check all which are appropriate)
	<pre>X State Water Control Law X Clean Water Act X VPDES Permit Regulation (9 VAC 25-31-10 et seq.) X EPA NPDES Regulation (Federal Register) EPA Effluent Guidelines (40 CFR 133 or 400 - 471) X Water Quality Standards (9 VAC 25-260-5 et seq.) Wasteload Allocation from a TMDL or River Basin Plan</pre>
18.	EFFLUENT LIMITATIONS/MONITORING: Provide all limitations and monitoring requirements being placed on each outfall.
	SEE TABLE II - ATTACHMENT 5

19. EFFLUENT LIMITATIONS/MONITORING RATIONALE: Attach any analyses of an outfall by individual toxic parameter. As a minimum, it will include: statistics summary (number of data values, quantification level, expected value, variance, covariance, 97th percentile, and statistical method); wasteload allocation (acute, chronic and human health); effluent limitations determination; input data listing. Include all calculations used for each outfall and set of effluent limits and those used in any model(s). Include all calculations/documentation of any antidegradation or antibacksliding issues in the development of any limitations; complete the review statements below. Provide a rationale for limiting internal waste streams and indicator pollutants. Attach chlorine mass balance calculations, if performed. Attach any additional information used to develop the limitations, including any applicable water quality standards calculations (acute, chronic and human health).

### OTHER CONSIDERATIONS IN LIMITATIONS DEVELOPMENT:

<u>VARIANCES/ALTERNATE LIMITATIONS</u>: Provide justification or refutation rationale for requested variances or alternatives to required permit conditions/limitations. This includes, but is not limited to: waivers from testing requirements; variances from technology guidelines or water quality standards; WER/translator study consideration; variances from standard permit limits/conditions.

N/A

**SUITABLE DATA:** In what, if any, effluent data were considered in the establishment of effluent limitations and provide all appropriate information/calculations.

All suitable effluent data were reviewed.

ANTIDEGRADATION REVIEW: Provide all appropriate information/calculations for the antidegradation review.

The receiving stream has been classified as tier 1; therefore, no further review is needed. Permit limits have been established by determining wasteload allocations which will result in attaining and/or maintaining all water quality criteria which apply to the receiving stream, including narrative criteria. These wasteload allocations will provide for the protection and maintenance of all existing uses.

ANTIBACKSLIDING REVIEW: Indicate if antibacksliding applies to this permit and, if so, provide all appropriate information.

There are no backsliding issues to address in this permit (i.e., limits as stringent or more stringent when compared to the previous permit).

SEE ATTACHMENT 6

20. **SPECIAL CONDITIONS RATIONALE:** Provide a rationale for each of the permit's special conditions.

SEE ATTACHMENT 7

21. TOXICS MONITORING/TOXICS REDUCTION AND WET LIMIT SPECIAL CONDITIONS RATIONALE:

Provide the justification for any toxics monitoring program and/or toxics reduction program and WET limit.

SEE ATTACHMENT 8

22. <u>SLUDGE DTSPOSAL PLAN</u>: Provide a description of the sludge disposal plan (e.g., type sludge, treatment provided and disposal method). Indicate if any of the plan elements are included within the permit.

N/A

23. <u>MATERIAL STORED</u>: List the type and quantity of wastes, fluids, or pollutants being stored at this facility. Briefly describe the storage facilities and list, if any, measures taken to prevent the stored material from reaching State waters.

SEE ATTACHMENT 9

24. RECEIVING WATERS INFORMATION: Refer to the State Water Control Board's Water Quality Standards [e.g., River Basin Section Tables (9 VAC 25-260-5 et seq.). Use 9 VAC 25-260-140 C (introduction and numbered paragraph) to address tidal waters where fresh water standards would be applied or transitional waters where the most stringent of fresh or salt water standards would be applied. Attach any memoranda or other information which helped to develop permit conditions (i.e. tier determinations, PReP complaints, special water quality studies, STORET data and other biological and/or chemical data, etc.

SEE ATTACHMENT 10

25. <u>305(b)/303(d) Listed Segments</u>: Indicate if the facility discharges to a segment that is listed on the current 303(d) list and, if so, provide all appropriate information/calculations.

This facility discharges directly to unnamed tributary of the York River and directly to the York River, and to Chisman Creek and Wormley Creek. This receiving stream segment has been listed in Category 5 of the 305(b)/303(d) list for non-attainment of: 1)the dissolved oxygen standard for open water-summer, 2) fish consumption due to PCB in fish tissue, 3)aquatic life use - dissolved oxygen, estuarine bioassessments, aquatic plants (macrophytes), 4) shallow-water submerged aquatic vegetation - aquatic plants (macrophytes). EPA approved the Chesapeake Bay TMDL December 29, 2010 for: nitrogen, phosphorus, TSS. TMDL report for shellfish areas listed due to bacterial contamination, approved August 2, 2006 for fecal coliform and enterococci. The facility was not assigned individual waste load allocations.

The permit contains water quality based limits for TSS and TP and water quality monitoring for enterococci. The permit contains a TMDL reopener to allow the permit to be modified in the future to address individual waste load allocations.

26. CHANGES TO PERMIT: Use TABLE III(a) to record any changes from the previous permit and the rationale for those changes. Use TABLE III(b) to record any changes made to the permit during the permit processing period and the rationale for those changes [i.e., use for comments from the applicant, VDH, EPA, other agencies and/or the public where comments resulted in changes to the permit limitations or any other changes associated with the special conditions or reporting requirements].

SEE ATTACHMENT 11

27. NPDES INDUSTRIAL PERMIT RATING WORKSHEET:

TOTAL SCORE: 600 SEE ATTACHMENT 12

28. <u>DEQ PLANNING COMMENTS RECEIVED ON DRAFT PERMIT</u>: Document any comments received from DEQ planning.

The discharge is in conformance with the existing planning documents for the area.

The discharge is not addressed in any planning document but will be included when the plan is updated.

29. <u>PUBLIC PARTICIPATION</u>: Document comments/responses received during the public participation process. If comments/responses provided, especially if they result in changes to the permit, place in the attachment.

<u>VDH/DSS COMMENTS RECEIVED ON DRAFT PERMIT</u>: Document any comments received from the Virginia Dept. of Health and the Div. of Shellfish Sanitaiton and noted how resolved.

The VDH reviewed the application and waived their right to comment and/or object on the adequacy of the draft permit.

The DSS has no comments on the application/draft permit.

**EPA COMMENTS RECEIVED ON DRAFT PERMIT:** Document any comments received from the U.S. Environmental Protection Agency and noted how resolved.

EPA waived the right to comment and/or object to the adequacy of the draft permit.

OR

EPA has no objections to the adequacy of the draft permit.

OR

By letter dated \_\_\_\_\_, the EPA provided the following comments:

ADJACENT STATE COMMENTS RECEIVED ON DRAFT PERMIT: Document any comments received from an adjacent state and noted how resolved.

Not Applicable.

OTHER AGENCY COMMENTS RECEIVED ON DRAFT PERMIT: Document any comments received from any other agencies (e.g., VIMS, VMRC, DGIF, etc.) and noted how resolved.

Not Applicable.

OTHER COMMENTS RECEIVED FROM RIPARIAN OWNERS/CITIZENS ON DRAFT PERMIT: Document any comments received from other sources and note how resolved.

The application and draft permit have received public notice in accordance with the VPDES Permit Regulation, and no comments were received.

OR

The application and draft permit have received public notice in accordance with the VPDES Permit Regulation. Section 9 VAC 35-31-310 of the VPDES Permit Regulation states, in part, "The Board shall hold a public hearing whenever it finds, on the basis of requests, a significant degree of public interest in a draft permit(s)."

DESCRIBE PN COMMENTS AND RESOLUTIONS. PROVIDE PUBLIC HEARING DATE AND REFERENCE BACKGROUND MEMORANDUM, IF APPROPRIATE.

PUBLIC NOTICE INFORMATION: Comment Period: Start Date End Date

Persons may comment in writing or by e-mail to the DEQ on the proposed issuance/reissuance/modification of the permit within 30 days from the date of the first notice. Address all comments to the contact person listed below. Written or e-mail comments shall include the name, address, and telephone number of the writer, and shall contain a complete, concise statement of the factual basis for comments. Only those comments received within this period will be considered. The Director of the DEQ may decide to hold a public hearing if public response is significant. Requests for public hearings shall state the reason why a hearing is requested, the nature of the issues proposed to be raised in the public hearing and a brief explanation of how the requestor's interests would be directly and adversely affected by the proposed permit action.

All pertinent information is on file and may be inspected, and arrangements made for copying by contacting Melinda Woodruff at: Department of Environmental Quality (DEQ), Tidewater Regional Office, 5636 Southern Boulevard, Virginia Beach, VA 23462. Telephone: 757-518-2174 E-mail: Melinda.Woodruff@deq.virginia.gov

Following the comment period, the Board will make a determination regarding the proposed issuance/reissuance/modification. This determination will become effective, unless the Director grants a public hearing. Due notice of any public hearing will be given.

30. ADDITIONAL FACT SHEET COMMENTS/PERTINENT INFORMATION:

### ATTACHMENT 1

SITE INSPECTION REPORT/MEMORANDUM

Facility:	DOMINION – YORKTOWN POWER STATION
County/city;	YORK COUNTY

VPDES NO. VA0004103

# DEPARTMENT OF ENVIRONMENTAL QUALITY WASTEWATER FACILITY INSPECTION REPORT PART 1

Inspection date:		Au	igust 27, 20	009	D	ate for	n complet	09				
Inspection by:			Clyde Gant	t	In	rspecti	on agency	:		DEQ/TRO	)	
Time spent:		8 Hours		A	nnoun	ced Inspec	tion:	[ ] Yes	[X] No			
Reviewed by: Kenneth T. Raum  Present at inspection:  Bruce Easley – Sr. Env. Con  FACILITY TYPE:  ( ) Municipal  (X) Industrial  ( ) Federal						Pho	tographs t	aken at site	? []Yes	[X] No		
Present at inspection:		Bruce E	asley – Sr. l	Env. C	omplian	ce Coo	rd.					
FACILITY TYPE:						FAC	ILITY CL	ASS:				
( ) Municipal		<u> </u>				(X) Major						
(X) Industrial						()	Minor					
( ) Federal						()	Small	-			·	
( ) VPA/NDC		-				()	High Prio	rity (	) Low Priorit	У		
TYPE OF INSPECTION:				Part State Control		Service Control of the Control of th						
Routine	X	Rei	nspection				Co	mpliance/a	ssistance/con	nplaint		
Date of previous inspectio	n:		April 19, 2007			Agency:						
Last Month Average: Effluent - 002		TP (mg/l)	0.05	C (mg	1.	<ql< td=""><td></td><td>Flow MGD)</td><td>658</td><td>pH (s.u.)</td><td>7.56</td></ql<>		Flow MGD)	658	pH (s.u.)	7.56	
		Other:					·					
Last Quarter Average: Effluent - 002		TP (mg/l)	0.05	C (m	12 g/l)	<ql< td=""><td></td><td>Flow MGD)</td><td>654</td><td>pH (s.u.)</td><td>7.56 – 7.79</td></ql<>		Flow MGD)	654	pH (s.u.)	7.56 – 7.79	
en en menne en el mestre sen propieta de la composició de la composició de la composició de la composició de l En en la composició de la		Other:										
Data verified in preface:			Upda	ated?				NO C	HANGES?		X	
Has there been any new co	onstructi	on?						YES		NO	X	
If yes, were the plans and					-			YES		NO		
DEQ approval date:	-:			<del>-</del>								
COPIES TO: (X) DEQ/T	RO; (X)	DEQ/OW	CP; (X) OV	VNER	; () OPE	ERATO	R; ()EPA	-Region III;	() Other:			

Storm Water P3 available and up dated? PIII, F. & G.	YES	x	NO	
Outfalls identified in SWP3? Site Map with Drainage and Flows available? PIII, B.2.c.1-10	YES	х	NO	
If there has been any new construction, were the plans and specifications approved and the SWP3 amended? PII, J.1.	YES	N/A	NO	
Housekeeping and Preventive Maintenance? PIII, B.6.b (1), (a) & (c)	YES	X	NO	
Quarterly Visual Examination of SW Quality? Results available? Pl, A.1.a.	YES	х	NO	
Inspections? (1/3M) PIII, B.6.b. (1) (e)	YES	х	NO	
Training (Annual)? PIII, B.6.b. (1) (f)	YES	X	NO	
Non-stormwater Certification? PIII, D.1.a.	YES	N/A	NO	
Comprehensive Site Evaluation and Report. Certification of Compliance or issues of non-compliance? PIII, E.	YES	х	NO	
Oil or other Hazardous Spills? PIII, B.4. & B.6.b. (1)(d)	YES	X	NO	

VA0004103

				PLANT	RECORDS							
	И	<i>ИІСН О</i>	F THE FOLI	LOWING	RECORDS DOE	ES THE PI	ANT M	AINTAIN	<i>1?</i>			
	Operational logs for industrial discharges YES X										NA	
	Instrument maintenance and o	alibratio	n				YES	X	NO		NA	
	Mechanical equipment mainte	enance		s.		:	YÉS	X	NO		NA	
1.	Industrial waste contribution (	(municip	al facilities)	·			YES		NO		NA	Х
			WHAT DO	ES THE (	OPERATIONAL .	LOG CON	<i>ITAIN</i>					
	Visual Observations	X		Flow Mea	asurement	X		Labo	ratory Re	sults		Ż
2.	Process Adjustments	N/.	A (	Control C	alculations	N/A			Other?			
ОМЛ	MENTS:											
	WHA	T DO TH	E MECHAN	ICAL EQ	UIPMENT REC	ORDS CO	NTAIN?	>			NA	
	MFG. Instructions	X	X As Built Plans/specs X					Spare Parts Inventory				>
3.	Lube Schedules	X		Otl	ier?		Equipment/parts Suppliers				s ·	3
OMA	MENTS:											
ОМЛ	MENTS:						:					,
	WHICH OF THE FO	DLLOWIN	IG RECORD	S ARE A	THE PLANT &	AVAILAI	BLE TO	PERSO	NEL?		NA	
	Equipment Maintena	nce Reco	rds	X		Industri	al Cont	ributor R	ecords	,		
4.	Operational Log	x	Sampling/testing Records			X		Instrume	entation R	tecords		7
5.	Records not normally availab	le to per	sonnel at their location: None								•	
	Were the records reviewed d	uring the	inspection						YES	X	NO	
6.	Are records adequate and the O&M manual current?								v.ma		1,10	
<ul><li>7.</li></ul>	Are records adequate and the	O&M n	anual curre	nt?					YES	X	NO	

VA0004103 FACILITY: Dominion - Yorktown SAMPLING 1. Are sampling locations capable of providing representative samples? YES X NO Do sample types correspond to VPDES permit requirements? YES X NO 2. Do sampling frequencies correspond to VPDES permit requirements? YES X NO 3. X YES NO Does plant maintain required records of sampling? 4. YES NO NA X 5. Are composite samples collected in proportion to flow? Are composite samples refrigerated during collection? YES  $\mathbf{X}$ NO NA 6. YES  $\mathbf{X}$ NO NA 7. Does the plant run operational control tests? COMMENTS: TESTING Who performs the testing? Plant X Central Lab  $\mathbf{X}$ Commercial Lab 1. Name: IF THE PLANT PERFORMS ANY TESTING, PLEASE COMPLETE QUESTIONS 2-4 Hach Pocket Colorimeter 2. Which total residual chlorine method is used? YES  $\mathbf{X}$ NO Does plant appear to have sufficient equipment to perform required tests? 3. Does testing equipment appear to be clean and/or operable? YES NO 4. COMMENTS: See lab inspection report. FOR INDUSTRIAL FACILITIES WITH TECHNOLOGY BASED LIMITS ONLY Is the production process as described in permit application? If no, describe changes in NO YES X NA 1. comments section.

YES

YES

X

NO

NO

NA

NA

X

Are products/production rates as described in the permit application? If no list differences

COMMENTS: Outfalls 003, 004, 101, 102 & 103 have limits based on Federal Effluent Guidelines, which are technology based.

Has the Agency been notified of the changes and their impact on plant effluent? Date

2.

3.

in comments section.

agency notified:

	JTY: Dominion - Yorktown		VA00041
PRO	BLEMS IDENTIFIED AT LAST INSPECTION:	CORRECTED	NOT CORRECTED
1.	None noted.		
	·		
	SUMMARY		
INSP	ECTION COMMENTS:		
1.	Outfall 001 - Condenser Cooling Water (Pumped): No discharge.		
2.	Outfall 002 - Condenser Cooling Water (Weir Overflow): Small amount of foam; g	reenish color; no probl	ems noted.
3.	003/004 - Ash Sedimentation Ponds: No problems noted. See attached checklist.		<u>.</u>
4.	008 – Stormwater From Ash Handling Area: Actual ash loading area contained wit drains in this area have straw bales around the drop inlets.	h closed loop dust supp	ression system. Storm
5.	010 - Stormwater From Warehouse area: No discharge, no problems noted.		
6.	011 – Stormwater From South of Switchyard/Along RR Tracks: Coal noted along l Phragmites growing thickly in ditch, would appear to make it difficult to get a samp		
7.	012 – Stormwater from entrance area/part of ash haul road: No discharge, no probl	ems noted.	
8.	101 – "Finger" Ponds: Operated in series. See attached checklist.		
9.	102 – Metals Pond: Seldom used or discharges now that landfill leachate is dischar around edges. No discharge, no problems noted.	ged to HRSD system.	Phragmites growing
10.	103 – Coal Pile Runoff Pond: Distinct red color. Discharge into cooling canal appeattached checklist.	ars to precipitate iron (	lue to pH change. See
11.	106/107 – Parking Lot Drains near Main Buildings: No discharge, not problems n	oted. Parking lots clea	n.
12.	108 - Reboiler Building Parking Lot: No discharge, not problems noted.		
13.	202, 203 & 204 – 002 Pumps Area Sump, Sump Back-up & Seal Water: Seal water No discharges, no problems noted.	no longer used, pump	s now operate without it
14.	The facility was generally clean and appears well maintained.		
сом	IPLIANCE RECOMMENDATIONS FOR ACTION:		
1.	None. No deficiencies noted.		

UNIT PROCESS:	Ash Disposal Ponds
·	Outfalls 003 & 004

	PRIMARY	х	SECONDARY		TERTIARY				YES	NO	<b>N</b> A
1.	Number of units				3						
2.	Number units in ope	ration			3						
3.	Proper flow distribut	ion between	units						х		
4.	Sludge collection sy	stem workin	g properly?						х		
5.	Signs of short circuit	ing and/or o	verloads								х
6.	Effluent weirs level	<u>.</u>							х		
7.	Effluent weirs clean								х		
8.	Scum collection syst	em working	properly								х
9.	Influent/effluent baff	le system w	orking properly								X
10:	Chemical Used					Chemical /	Addition				х
11.	Effluent characterist	cs		i		Clear					
GENE	RAL CONDITION:		GOOD		FAIR		х	P	oor		

COMMENTS:

Stormwater from active ash landfill cells flows to the center pond. That pond overflows to both of the other ponds. No problems noted with 003 pond. 004 pond shallow with some algal growth.

		UNIT PROCESS:	Oii	RETENTION BASIN					
		· · · · · · · · · · · · · · · · · · ·					YES	NO	NA
1.	Number of units			1					
2.	Number units in operation	1 · · · · · · · · · · · · · · · · · · ·		1					
3.	Proper flow distribution be	etween units							х
4.	Sludge collection system working properly?								х
5.	Signs of short circuiting a	nd/or overloads						х	
6.	Effluent weirs level								х
7.	Effluent weirs clean		•						х
8.	Scum collection system w	orking properly		P			х		
9.	Influent/effluent baffle sys	tem working properly					х		
10.	Chemical Used			Chemica	l Addition				х
11.	Effluent characteristics		No Discharge						
GENEF	RAL CONDITION:	GOOD		FAIR	х	Р	OOR		

COMMENTS:

Sediment being removed from pond by excavator. Work performed in area that is contained and drains to basin. Several oil booms in place across basin. Oil skimmer working. Manual discharge to finger ponds. Receives discharge from bulk oil tank bermed area. Bermed area clean and dry.

UNIT PROCESS:	North & South Finger Ponds	
	OUTFALL 101	•

							YES	NO	NA
1.	Number of units		2						
2.	Number units in operation		2						
3.	Proper flow distribution between	en units					:		х
4.	Signs of short circuiting and/or	overloads						х	
5.	Effluent weirs level								х
6.	Effluent weirs clean								х
7.	Scum collection system working	g properly		- <u> </u>		<u>, , , , , , , , , , , , , , , , , , , </u>			х
8.	Influent/effluent baffle system	working properly					x		
9.	Chemical Used			Chemical A	Addition				х
10.	Effluent characteristics			Clear					
GENE	RAL CONDITION:	GOOD	FAI	R	х	P	OOR		

COMMENTS:

Receives flow from oil retention basin, power plant floor drains and ash loading area. The ponds operate in series, with the north pond flowing to the south pond and then discharging to the cooling canal. Duckweed in both ponds. Discharge is measured with an ultrasonic meter on the end of the discharge pipe. Last flowmeter calibration 12/3/08. There may be some discharge pipe infiltration as the pond was not overflowing into pipe, but there was a low volume discharge.

and the second s	The second secon
UNIT PROCESS:	COAL PILE RUNOFF POND
	Outfall 103

							YES	NO	NA
1.	Number of units	·	1						
2.	Number units in operation		1						
3.	Proper flow distribution between	en units							х
4.	Signs of short circuiting and/or	roverloads						х	
5.	Effluent weirs level			·					Х
6.	Effluent weirs clean								Х
7.	Scum collection system working	ng properly							. <b>X</b>
8.	Influent/effluent baffle system	working properly					х		
9.	Chemical Used	·		Chemical	Addition				х
10.	Effluent characteristics		Low vo	lume; red col	or.				
GENE	RAL CONDITION:	GOOD	FA	JR.	x	Р	OOR		

COMMENTS:

Wastewater in the pond has a distinct deep red color. Discharge into cooling canal becomes a mud colored plume. Change apparently due to differences in pH and possible iron precipitation.

UNIT PROCESS: EFFLUENT/PLANT OUTFALL.

				· · · · · · · · · · · · · · · · · · ·	_			YES	NO	NA
1.	Type of outfall		Sh	ore Based	х	Submerged	X			
		TYP	PE IF SHO	RE BASED:						
2.	Wingwall	Headwall	X	Rip Rap		Pipe				
3.	Flapper valve presen	it?						202		
4.	Erosion of bank area	1?					·		Х	
5.	Effluent plume visible	∍?						103	·	
	Condition of outfall a	and the supporting st	ructure?							
6.	GOOD	FAIR	х	POOR						
	FII	NAL EFFLUENT, EV	IDENCE	OF FOLLOWIN	G PROB	LEMS?				
	Oil sheen?		_						х	
	Grease?								х	
	Sludge bar?		••						Х	
	Turbid effluent?							103		
	Visible foam?					· · · · · · · · · · · · · · · · · · ·	· · ·	х		
7.	Unusual color?								х	

GENERAL CON	NDITION:	GOOD		FAIR	х	POOR	
COMMENTS:	Outfall 001 n	not used very often. Us	sually due t	o low flow			



### COMMONWEALTH of VIRGINIA

### DEPARTMENT OF ENVIRONMENTAL QUALITY

L. Preston Bryant, Jr. Secretary of Natural Resources TIDEWATER REGIONAL OFFICE 5636 Southern Boulevard, Virginia Beach, Virginia 23462 (757) 518-2000 Fax (757) 518-2009 www.deg.virginia.gov

David K. Paylor Director

Francis L. Daniel Regional Director

September 14, 2009

Ms. Cathy Taylor
Director, Electrical Environmental Services
5000 Dominion Blvd.
Glen Allen, VA 23060

Re: Inspection Report

Dominion - Yorktown Power Station (VA0004103)

Dear Ms. Taylor:

Enclosed is a copy of the report prepared for the inspection conducted at the subject Dominion facility on August 27, 2009. No problems or deficiencies were noted during the inspection.

If you have any questions regarding this report, please feel free to contact me at the above address, telephone (757) 518-2114, or email: clyde.gantt@deq.virginia.gov.

Sincerely,

Clyde K. Gantt

CAFO / Biosolids Inspector

Enclosure

cc: DEQ/OWCP: Steve Stell

FACILITY: Dominion - Yorktown

DEQ/TRO: File

# DEPARTMENT OF ENVIRONMENTAL QUALITY - WATER DIVISION LABORATORY INSPECTION REPORT

10/01

EACII	ITY NO:	INSPECTION DATE:	DDEVIOUS INSD. DATE		DDEMONO EMA			THE OPEN
FACIL	III NO.	INSPECTION DATE:	PREVIOUS INSP. DATE		PREVIOUS EVA	LUATIO	N:	TIME SPENT: 5 Hours
	004103	August 27, 2009	April 19, 2007		Deficienci	es		
Domini 1600 V			(X) MAJOR () MINOR () SMALL () HIGH PRIORITY () LOW PRIORITY	() (X) () ()	CILITY TYPE:  MUNICIPAL INDUSTRIAL FEDERAL COMMERCIAL VPA/NDC	. LAB	(X) ()	YANNOUNCED YES NO  -SCHEDULED YES NO YES NO YES NO
INSPE	CTOR(S):	<u> </u>	REVIEWERS:	$\top$	PRESENT AT INS	SPECTION	DN:	
Clyde	Gantt		Kenneth T. Raum		Dale Ludi - Chem	ist II		
		LABURATO	RY EVALUATION					HENCIES?
LAPOR	RATORY F	PECORDS					es	No sissi
		PLING & ANALYSIS					X	<u> </u>
		EQUIPMENT			<u></u>			
		ROCEDURES						X
<del>-</del>		AL CHLORINE ANALYSIS	PROCEDURES	-				X
	· · · · · · · · · · · · · · · · · · ·							
							<del></del>	
	·							
								-
	·							
					·			
					· · · · · · · · · · · · · · · · · · ·			
		· · · · · · · · · · · · · · · · · · ·						
	I		ALITY ASSURANCE/QUAL	ITY (	CONTROL			
Y/N		Y ASSURANCE METHOD	PARAMETERS			FRE	QUEN	CY
Υ		CATE SAMPLES						
		SAMPLES					,	
Y		ARD SAMPLES						
		SAMPLES				<u> </u>		
Y		E BLANKS						
	OTHER						···	
		IR QA DATA?		-	ciency () Defic		(X) NA	
		IPLES PROVIDED?	RATING: () No		ciency () Defic	iency	(X) NA	(
COPIES	TO: (X) DE	Q/TRO; (X) DEQ/OWCP; (X) OW	NER; () EPA-Region III; () Other	:				

		ů.				FACILITY	#: VA000	4103
LABO	RATORY RECORDS SECTION							
LABOF	RATORY RECORDS INCLUDE THE	FOLLO	WING:					
····	1		1		1			
Х	SAMPLING DATE	X	ANALYSIS DATE		1	ONITORING		
X	SAMPLING TIME	X	ANALYSIS TIME	X	1	MENT CALI		
Х	SAMPLE LOCATION	X	TEST METHOD		ļ	MENT MAIN		
				X	CERTIFIC	CATE OF A	NALYSI	S
WRITT	EN INSTRUCTIONS INCLUDE THE	E FOLLO	WING:					:
Х	SAMPLING SCHEDULES	Х	CALCULATIONS	X	ANALYS	IS PROCE	DURES	
			ili san kandharan pembasakan sast			YES	NO	N/A
DO ALL ANALYSTS INITIAL THEIR WORK?  DO BENCH SHEETS INCLUDE ALL INFORMATION NECESSARY TO DETERMINE RESULTS?								
DO BE	NCH SHEETS INCLUDE ALL INFO	DRMATIC	ON NECESSARY TO DETER	MINE RE	SULTS?	Х		
IS THE	DMR COMPLETE AND CORREC	T? MON	TH(S) REVIEWED: May – Ju	y, 2009			Х	
ARE ALL MONITORING VALUES REQUIRED BY THE PERMIT REPORTED?								
GENERAL SAMPLING AND ANALYSIS SECTION								
						YES	NO	N/A
ARE S	AMPLE LOCATION(S) ACCORDIN	IG TO PE	ERMIT REQUIREMENTS?			YES	NO	N/A
	AMPLE LOCATION(S) ACCORDIN			Guirnis Suns			NO	N/A
ARE S		RES API	PROPRIATE?			Х	NO	N/A
ARE S	AMPLE COLLECTION PROCEDU	RES API	PROPRIATE? E?			X	NO	N/A
ARE S	AMPLE COLLECTION PROCEDUI	RES APF DEQUAT TO PER	PROPRIATE? E? MIT REQUIREMENTS?			X X X	NO	N/A X
ARE S IS SAM IS FLC ARE C	AMPLE COLLECTION PROCEDUING  MPLE EQUIPMENT CONDITION ALL  DW MEASUREMENT ACCORDING	RES APP DEQUAT TO PER NTATIVI	PROPRIATE? E? RMIT REQUIREMENTS? E OF FLOW?			X X X	NO	
ARE S IS FLO ARE C ARE S IF ANA	AMPLE COLLECTION PROCEDUING  MPLE EQUIPMENT CONDITION ALL  DW MEASUREMENT ACCORDING  COMPOSITE SAMPLES REPRESE	RES APP DEQUAT TO PER NTATIVI RESERVA	PROPRIATE? E? RMIT REQUIREMENTS? E OF FLOW? ATION ADEQUATE? CATION, ARE SHIPPING PR	OCEDUF	RES	X X X	NO	
ARE S IS SAM IS FLC ARE C ARE S IF ANA ADEQU	AMPLE COLLECTION PROCEDUING  MPLE EQUIPMENT CONDITION ALL  OW MEASUREMENT ACCORDING  COMPOSITE SAMPLES REPRESE  AMPLE HOLDING TIMES AND PROCEDUING  ALYSIS IS PERFORMED AT ANOT	RES APP DEQUAT TO PER NTATIVI RESERVA	PROPRIATE? E? RMIT REQUIREMENTS? E OF FLOW? ATION ADEQUATE? CATION, ARE SHIPPING PR	OCEDUF	RES	X X X X	NO	
ARE S IS SAM IS FLC ARE C ARE S IF ANA ADEQU	AMPLE COLLECTION PROCEDUING MPLE EQUIPMENT CONDITION ALL DW MEASUREMENT ACCORDING COMPOSITE SAMPLES REPRESE CAMPLE HOLDING TIMES AND PROCEDUING ALYSIS IS PERFORMED AT ANOT UATE? LIST PARAMETERS AND	RES APP DEQUAT TO PER NTATIVI RESERVA	PROPRIATE? E? RMIT REQUIREMENTS? E OF FLOW? ATION ADEQUATE? CATION, ARE SHIPPING PR	OCEDUF	RES	X X X X	NO	
ARE S IS SAM IS FLO ARE C ARE S IF ANA ADEQU	AMPLE COLLECTION PROCEDUING MPLE EQUIPMENT CONDITION ALL DW MEASUREMENT ACCORDING COMPOSITE SAMPLES REPRESE CAMPLE HOLDING TIMES AND PROCEDUING ALYSIS IS PERFORMED AT ANOT UATE? LIST PARAMETERS AND	RES APP DEQUAT TO PER NTATIVI RESERVA HER LO NAME 8	PROPRIATE? E? EMIT REQUIREMENTS? E OF FLOW? ATION ADEQUATE? CATION, ARE SHIPPING PR ADDRESS OF LAB:	OCEDUF	RES	X X X X		X
ARE S IS SAM IS FLO ARE C ARE S IF ANA ADEQU  LABOR	AMPLE COLLECTION PROCEDUING MPLE EQUIPMENT CONDITION ALL DW MEASUREMENT ACCORDING COMPOSITE SAMPLES REPRESE CAMPLE HOLDING TIMES AND PROMOTE SETTING MATERIAL PARAMETERS AND MATERIAL PARAMETERS AND MATORY EQUIPMENT SECTION	RES APP DEQUAT TO PER INTATIVE RESERVA HER LO NAME 8	PROPRIATE? E? RMIT REQUIREMENTS? E OF FLOW? ATION ADEQUATE? CATION, ARE SHIPPING PRADDRESS OF LAB: ERATING RANGE?	OCEDUF	RES	X X X X X		X

ARE ANALYTICAL BALANCE(S) ADEQUATE?

<sup>\*</sup> SEE LABORATORY INSPECTION REPORT SUMMARY PAGE FOR DETAILS REGARDING ASTERISKED ITEMS

# DEPARTMENT OF ENVIRONMENTAL QUALITY - WATER DIVISION LABORATORY INSPECTION REPORT SUMMARY

	LABORATORY INSPECT	<mark>TON RE</mark> /01	PORT S	UMMARY		
FACILITY NAME:	Dominion - Yorktown Power Station	VPDES	S NO:	VA0004103	INSP. DATE:	8/27/09
LABO	RATORY RATING		NO DE	FICIENCIES		
		x	DEFIC	IENCIES		
and the second state of the second se	LABORATOR	Y REC	CORDS			
reported the maxing for sample collected.  2. For parameters the actual QL concerned as 0.05 maximum results should have for Total Fe was regults should have	Records section has deficiencied mum semi-annual value for TSS to ed March 3, 2009. It stat do not have a permit specific centration (e.g. <xx). 250="" <="" a="" analyses="" as="" been="" certificate="" certificates="" dmr="" i.="" maying="" of="" on="" reported="" seported="" td="" the="" to="" ug=""></xx).>	o be 2. ied QL / DMR report an aver te of an	3 mg/l. , the re for out results age of	The actual n sults must be fall 002, the T of 0.05 mg/l. F <0.05 mg/l. F reports a res	naximum was reported as otal Phospho and <0.05 m For outfall102	s 9.7 mg/l, less than orus was g/l. The 2, the result
	GENERAL SAMPLII	NG AN	ID AN	ALYSIS		
The General Sam	pling and Analysis section has no	defici	encies.			
	LABORATOR)	/ EQU	IPMEN			
The Laboratory Ed	quipment section has no deficienc	cies.				,
	PARAMETER	RSUM	MARY			
The analysis for th	p e parameter of pH has no deficie					

Total Residual Chlorine (TRC)

The analysis for the parameter of TRC has no deficiencies.

DEPARTMENT OF ENVIRONMENTAL QUALITY - WATER DIVISION EQUIPMENT TEMPERATURE LOG/THERMOMETER VERIFICATION CHECK SHEET 1/08

					200	2						-	
FACILITY NAME:	Dominion - Yorktown Power St	rktown F	ower St	ation	VPDES NO:		VA0004103	103	DATE:		August 27, 2009	60	
EQUIPMENT	RANGE	<u> </u>	N.	INSPECT	CHE	CHECK&	CORRECT	ECT	ANN	ANNUAL THERMOMETER VERIFICATION	IETER VERIFIC	ATION	
		₹ 	n n	KEADING:	 2 	LOG DAILY	INCREMENT		Is the NIST / N	is the NIST / NIST-Traceable Reference	Reference	'λ'	ΥN
		·· ·		,	····			·	I hermometer expiration date	I hermometer within the manufacturer's expiration date or recertified yearly?	iufacturer's rearly?		>
									DATE CHECKED	MARKED	CORR	INSPECT	CT.
·		<b>&gt;</b>	Z		<b>\</b>	Z	<b>\</b>	z		N +	၁	ပ္	
SAMPLE REFRIGER.	1-6°C	<b>\</b>		2.6	*		<b>\</b>		6/12/09	¥	0.0		
pH METER	±1°C	Υ		23.5					1/13/09	>	0.4	18.4	
												-	

PROBLEMS: \* Refrigerator checked Monday - Friday.

# DEPARTMENT OF ENVIRONMENTAL QUALITY - WATER DIVISION SAMPLE ANALYSIS HOLDING TIME/CONTAINER/PRESERVATION CHECK SHEET Revised 3/08 140 CFR Part 136.3 Table III

FACILITY NAME:	Dominic	on – Yorktov	Revised 3/08 [40]  Dominion – Yorktown Power Station	Revised 3/08 [40 CFR, Part 136.3, Table II]  n Power Station  VPDES NO	VPDES NO	VA0004103	DATE: A	Aug. 27, 2009	600
	HOLDING TIMES			SAMPLE	SAMPLE CONTAINER	PRES	PRESERVATION		
PARAMETER	APPROVED	MET?	LOGGED?	ADEQ. VOLUME	APPROP. TYPE	APPROVED	MET?	СИЕСКЕВ?	KED?
		Z ≻	z ≻	N	Υ		z ≻	>	z
TSS	7 DAYS	×	×	×	×	၁ွ့ၜ	×	×	
FECAL COLIFORM / E. coli / Enterococci	6 HRS & 2 HRS TO PROCESS	N/A				10°C (1 HOUR)+ 0.008% Na <sub>2</sub> S <sub>2</sub> 0 <sub>3</sub>			
Hd	15 MIN.	×	×	×	×	N/A	×	×	
CHLORINE	15 MIN.	×	×	×	×	N/A	×	×	
TEMPERATURE	IMMERSION STAB.	N/A	-			N/A			
OIL & GREASE	28 DAYS	×	×	×	×	6°C + H <sub>2</sub> SO <sub>4</sub> /HCL pH<2	×	×	
ТРН		×	×	×	×				
TOTAL PHOS.	28 DAYS	×	×	×	×	6°C+ H₂S0₄ pH<2	×	×	
METALS (except Hg)	6 MONTHS	×	×	×	×	HNO <sub>3</sub> pH<2	×	×	
PROBLEMS:						PROBLEMS:	-		

ANALYST:	Dale Ludi	VPDES NO	VA0004103

Meter: Corning 440

Parameter: Hydrogen Ion (pH) 1/08

Method: Electrometric

### METHOD OF ANALYSIS:

X	

18<sup>th</sup> Edition of Standard Methods – 4500-H<sup>\*</sup> B

21st or Online Editions of Standard Methods – 4500-H<sup>+</sup> B (00)

	pH is a method-defined analyte so modifications are not allowed. [40 CFR Part 136.6]	Υ	N
1)	ls a certificate of operator competence or initial demonstration of capability available for <a href="mailto:each_analyst/operator">each_analyst/operator</a> performing this analysis? <b>NOTE</b> : Analyze 4 samples of known pH. May use external source of buffer (different lot/manufacturer than buffers used to calibrate meter). Recovery for each of the 4 samples must be +/- 0.1 SU of the known concentration of the sample. [SM 1020 B.1]		
2)	ls the electrode in good condition (no chloride precipitate, scratches, deterioration, etc.)? [2.b/c and 5.b]		
3)	Is electrode storage solution in accordance with manufacturer's instructions? [Mfr.]	Х	
4)	Is meter calibrated on at least a daily basis using three buffers all of which are at the same temperature? [4.a] NOTE: Follow manufacturer's instructions.		
5)	After calibration, is a buffer analyzed as a check sample to verify that calibration is correct?  Agreement should be within +/- 0.1 SU. [4.a]		
6)	Do the buffer solutions appear to be free of contamination or growths? [3.1]	e buffer solutions appear to be free of contamination or growths? [3.1]	
7)	Are buffer solutions within the listed shelf-life or have they been prepared within the last 4 weeks? [3.a]		
8)	Is the cap or sleeve covering the access hole on the reference electrode removed when measuring pH? [Mfr.]		
9)	For meters with ATC that also have temperature display, is the thermometer verified annually? [SM 2550 B.1]	х	
10)	Is temperature of buffer solutions and samples recorded when determining pH? [4.a]	х	
11)	ls sample analyzed within 15 minutes of collections? [40 CFR Part 136]	Х	
12)	Is the electrode rinsed and then blotted dry between reading solutions (Disregard if a portion of the next sample analyzed is used as the rinsing solution.)? [4.a]	х	
13)	Is the sample stirred gently at a constant speed during measurement? [4.b]	х	
14)	Does the meter hold a steady reading after reaching equilibrium? [4.b]	Х	

PROBLEMS:



L. Preston Bryant, Jr. ecretary of Natural Resources 757) 518-2009

12)

13)

14)

Pillow addition? [Hach 11.2]

TIDEWATER REGIONAL OFFICE 5636 Southern Boulevar ( ) 14 14 16 North 2341 T

David K. Paylor Director

www.deq.virginia.gov

DEPARTMENT OF

Francis L. Daniel Regional Director

L QUALITY

X

X

N/A

ANALYST:		Dale Ludi	VPDES NO.	VA0004103		
<u>Instri</u>	ument:	Hach DR820 Parameter: Total Residual Chlo Method: DPD Colorimetric (HACH Poo 1/08				
METH	OD OF A	ANALYSIS:				
X	HACH	Manufacturer's Instructions (Method 8167) plus an edition of	Standard Method	S		
	18 <sup>th</sup> Ed	lition of Standard Methods 4500-CI G				
	21 <sup>st</sup> Ed	lition of Standard Methods 4500-CI G (00)				
	·				Υ	N
1)	analys numbe	ertificate of operator competence or initial demonstration of cast <u>/operator</u> performing this analysis? <b>NOTE</b> : Analyze 4 sampler or source that is different from that used to prepare calibra	es of known TRO	C. Must use a lot	х	
2)	Are th	e DPD PermaChem™ Powder Pillows stored in a cool, dry p	lace? [Mfr.]		Х	
3)	Are th	e pillows within the manufacturer's expiration date? [Mfr.]			Х	
4)		uffering capability of DPD pillows been checked annually? (Pen 6 and 7) [Mfr.]	illows should adj	ust sample pH to	x	
5)	When	pH adjustment is required, is H <sub>2</sub> SO <sub>4</sub> or NaOH used? [Hach 1	11.3.1]		Х	
6)	Are ce	ells clean and in good condition? [Mfr]			Х	
7)	Is the	low range (0.01 mg/L resolution) used for samples containing	g residuals from (	0.2.00 mg/L? [Mfr.]	Х	
8)	and a	bration curve developed (may use manufacturer's calibration) low standard? NOTE: May use manufacturer's installed calib ne standards for daily calibration verifications. [18 <sup>th</sup> ed 1020 B	ration and comm	ercially available	х	
9)	Is the	10-mL cell (2.5-cm diameter) used for samples from 0-2.00 r	ng/L? [Mfr.]		Х	
10)	Is met	ter zeroed correctly by using sample as blank for the cell use	ed? [Mfr.]		Х	
11)		instrument cap placed correctly on the meter body when the	meter is zeroed	and when the	Х	

Is the DPD Total Chlorine PermaChem™ Powder Pillow mixed into the sample? [Hach 11.1]

If read-out is flashing [2.20], is sample diluted correctly, and then reanalyzed? [Hach 1.2 & 2.0]

Is the analysis made at least three minutes but not more than six minutes after PermaChem™ Powder

PROBLEMS:



# COMMONWEALTH of VIRGINIA

### DEPARTMENT OF ENVIRONMENTAL QUALITY

L. Preston Bryant, Jr. Secretary of Natural Resources

**TIDEWATER REGIONAL OFFICE** 5636 Southern Boulevard, Virginia Beach, Virginia 23462 (757) 518-2000 Fax (757) 518-2009 www.deg.virginia.gov

David K. Paylor Director

Francis L. Daniel Regional Director

Ms. Cathy Taylor Director, Electrical Environmental Services 5000 Dominion Blvd. Glen Allen, VA 23060

Re: Laboratory Inspection

Dominion – Yorktown Power Station (VA0004103)

Dear Ms. Taylor:

Enclosed is a copy of the inspection report for the laboratory evaluation conducted on August 27, 2009. Please note that the Laboratory Evaluation Section of the report identifies that the Laboratory Records Section requires correction. The report identifies the specific deficiencies and makes recommendations for corrective measures.

In view of the significance attached to proper sampling and analysis of samples for use in complying with the terms of your VPDES/VPA permit, please review the attached report and make the appropriate corrections to ensure permit compliance. To avoid possible enforcement action, within fifteen (15) days of receipt of this letter send a written notification to this office of the corrective measures that you have implemented. If you have not taken corrective action and/or responded to this office in writing by the above deadline, this matter will be referred to the Regional Compliance Auditor and a Warning Letter may be issued.

If you have any questions regarding this report, please contact me or Mr. Kenneth T. Raum at the above address, telephone (757) 518-2114, or email: clyde.gantt@deq.virginia.gov.

Sincerely,

Clyde K. Gantt

CAFO / Biosolids Inspector

cc: DEQ/OWCP: Steve Stell DEQ/TRO: File

**Dominion Generation** 1600 Waterview Road, Yorktown, VA 23692 Web Address: www.dom.com

July 7, 2009

# CERTIFIED MAIL 7007 0710 0004 0134 7546 RETURN RECEIPT REQUESTED

Virginia Dept. of Environmental Quality Water Division Tidewater Regional Office 5636 Southern Blvd. Virginia Beach, VA 23462

Re: YORKTOWN POWER STATION - NPDES DISCHARGE MON FOR JULY 2009

Sir or Madam:

Attached are the originals and one copy of the July 2009 NPDES Dis-Station.

As you know, these reports are required by and prepared specifically Quality (VDEQ). They represent truly, accurately, and completely the analyses required by the State to be performed or submitted, but of assertion of the accuracy of any instrument, readings or analytical suitability of any analytical or measurement procedure.

Additional laboratory analyses for outfall 103 are attached. Some of our VPDES permit, but are reported in accordance with Section II. this period will be sent under a separate cover by our corporate Envir

As discussed with Mark Sauer of your office on July 28, we are providing the following information.

On July 28, a truck driver accidently backed into an overhead Reverse Osmosis pipeline. The line was secured Within a few minutes, but approximately 20 gallons of water entered a storm drain leading to outfall 106. No negative environmental impact has been observed.

5636 Southern Boulevard Virginia Beach, VA 23462

Water Division - TRO

VA Department of Environmental Quality

The following outfall(s) do not have Discharge Monitoring Reports for this reporting period:

Outfall	Identification	Reason	
008 & 014	Stormwater	2nd. Quarter sampling performed 04/09	
010	Stormwater	Annual sampling performed 01/09	
011	Stormwater	Annual sampling done 04/09	
012	Stormwater	Annual sampling done 04/09	
103	Coal Pile Basin	Monthly TSS 2.1ppm. Additional analyses attached.	
106	Stormwater	Annual sampling performed 01/09	
107,108,110	Stormwater	Annual sampling performed 01/09	


If you have any questions or desire additional information, please do not hesitate to contact Richard Smith at (757) 898-2544.


Sincerely.


Joshua J. Bennett Station Director

## ATTACHMENT 2

DISCHARGE LOCATION/TOPOGRAPHIC MAP










### ATTACHMENT 3

SCHEMATIC/PLANS & SPECS/SITE MAP/ WATER BALANCE



<ÿ





### ATTACHMENT 4

TABLE I - DISCHARGE/OUTFALL DESCRIPTION

NUMBER AND DESCRIPTION OF OUTFALLS

OUTFALL NO.	DISCHARGE LOCATION	DISCHARGE SOURCE	TREATMENT (2)	FLOW (3)
001	37°13′1″ 76°27′27″	Condenser Cooling Water; internal outfalls 101, 102, 103, 104, 105, 106, 107, 108,109, 110, 111, 112	Thermal diffusion	476.3 MGD
101*	37°12′54″ 76°27′33″	Finger Ponds (low volume wastes including but not limited to: boiler blowdown, surge tank overflow, pyrite hydrobin overflow, Unit 3 boiler seal trough, demineralizer wastes, stack washes, mechanical dust collector drains, air preheater drains, boiler slope washes, pan washes, localized boiler tube rinsing, clinker removal, acid and caustic tank dike, ammonia tank 9no longer in use) dike and other sources of storm water, oil retention pond)	Flow equalization, sedimentation, skimming, floatation (oil retention pond only)	2.41 MGD
102*	37°13′0″ 76°27′24″	Metals cleaning pond: Units 1-3 ESP wash, air preheater wash, units 1- 3 boiler wash, ductwork wash, turbine wash, boiler tube washdown, coal fly ash leachate tank, alternative flow for Low volume waste	Sedimentation	0.24 MGD
103*	37°12′59″ 76°27′28″	Storm water - coal pile runoff, vehicle washwater, "rainbird" water used in dust suppression activities (potable)	Sedimentation	1.538 MGD
104*	37°13′41″ 76°27′9″	Coal flyash leachate tank Internal discharge to 102- metal cleaning pond	Sedimentation	Currently discharges to HRSD (0.020 MGD)

OUTFALL	DISCHARGE	DISCHARGE SOURCE	TREATMENT	FLOW
NO.	LOCATION	(1)	(2)	(3) 4 (C
105*	37°11′12″	Dewatering of outfall		Varies
	76°28′12″	pumps during maintenance		
106*	37°13′0″	Storm water from the		Varies
	76°27′45″	area in the vicinity of		
		the units 1 & 2 turbine	,	
		building, administrative		
		building, and		
		maintenance building		
		(regulated industrial		
		activity)	•	·
107*	37°13′0″	Storm water from roof		Varies
	76°27′45″	drains, main station		
·		transformers, and a		
		portion of the		
		switchyard (regulated	4	
		industrial activity)	,	
		(substantially identical		
		to 108 and 110)		
108*	37°13′0″	Storm water from paved		Varies
	76°27′45″	areas in the area of the		Valies
		head of the discharge		
		canal (regulated	j	
		industrial	İ	
		activity) (substantially		
		identical to 107 and		×
		110)		
109*	37°11′21″	Storm water from the		Varies
]	76°28′13″	south side of the		
		condenser cooling water		
		canal, including oil		
		transfer areas and	•	
	·	petroleum storage areas		
		(regulated industrial		
		activity)		
110*	37°13′0″	Storm water from the		Varies
	76°22 <b>′</b> 45″	north side of the		
<u> </u>	ŀ	condenser cooling water		
		canal, including paved		
		areas near and easement		
		of the oil company and		
		the old guardhouse		
		(regulated industrial		
		activity) (substantially		
		identical to 107 and		1
		108)		
112*	37°11′21″	Storm water from the		Varies
	76°28′12″	area adjacent to the		
		fence line next the		_
1	·	refinery property line,		·
		not associated with		
		industrial activity		
		<u> </u>		

OUTFALE NO.	DISCHARGE LOCATION	DISCHARGE SOURCE (1)	TREATMENT.	FLOW
002	37°13′1″ 76°27′27″	Weir discharge of condenser cooling water; all internal outfalls	Thermal diffusion	248.3 MGD
202*	37°11′22″ 76°28′12″	Outfall pumps pit sump		0 MGD Out of service
203*	37°11′21″ 76°28′12″	Outfall pumps pit sump back up		Varies
204*	37°11′21″ 76°26′14″	Outfall pumps cooling /sealing water		0.01152 MGD
111*	37°13′0″ 76°27′24″	Intake screen wash		1.872 MGD
205*	37°11′21″ 76°28′12″	Storm water		Varies
	37°11′21″ 76°28′12″	Sediment pond #1: storm water runoff from ash landfill, truckwash wastewater, runoff from dust suppression activities	Sedimentation and neutralization	1.472 MGD
004	37°11′18″ 76°28′7″	Sediment pond #2: storm water runoff from ash landfill	Sedimentation and neutralization	0.05 MGD
005	37°12′57″ 76°27′43″	Unit 1 condenser backwash		79.2 MGD
006	37°12′57″ 76°27′43″	Unit 2 condenser backwash		79.2 MGD
007	37°12′57″ 76°27′43″	Dewatering of intake pump structure and header	·	Varies
	37°12′57″ 76°27′45″	Storm water from Unit 3 stack and ash handling areas (regulated industrial activity) (substantially identical to outfall 014)	-	0.013 MGD
009	37°12′55″ 76°27′53″	Storm water from northwest corner of the station including gravel lots and grass areas (non-industrial)		0.007 MGD
010	37°12′40″ 76°27′50″	Storm water from warehouse area (regulated industrial activity)		0.005 MGD

OUTFALL	DISCHARGE	DISCHARGE SOURCE	TREATMENT	FLOW
NO.	LOCATION	(1)	(2)	(3) 12 32 54
011	37°11′55″ 76°28′4″	Storm water from switchyard, security building, coalyard service building, access roads, parking lots, maintenance building for coal yard, coal		Varies
		conveyors, coal shaker building, coal unloading building, fuel pumps (regulated industrial activity)		
012	37°12′0″ 76°27′49″	Storm water from area containing a portion of the ash haul road(regulated industrial activity)		0.006 MGD
013	37°12′3″ 76°27′50″	Storm water - not associated with a regulated industrial activity		0.089 MGD
014	37°12′57″ 76°27′44″	Storm water from area including the service road for intake cooling water pumps(regulated industrial activity) (substantially identical to outfall 008)		0.002 MGD
015	37°12′57″ 76°27′41″	Storm water from a cable trough located in the vicinity of cooling water intake pumps		0.003 MGD
016	37°12′57″ 76°27′43″	Intake leak collection pit		Varies
017	37°12′54″ 76°27′33″	Ash landfill hydrostatic pressure relief system under the center pond; uncontaminated groundwater		
		3		

<sup>(1)</sup> List operations contributing to flow

<sup>(2)</sup> Give brief description, unit by unit

<sup>(3)</sup> Give maximum 30-day average flow for industry and design flow for municipal \* Indicates internal outfall

### ATTACHMENT 5

TABLE II - EFFLUENT MONITORING/LIMITATIONS

### - INDUSTRIAL EFFLUENT LIMITATIONS/MONITORING TABLE II

OUTFALL # 001

Outfall Description: Condenser cooling water - outfall pumps discharge; internal outfalls 101, 102, 103,104, 105, 106, 107, 108, 109, 110, 112.

SIC CODE: 4911

Expiration :OI From: Issuance Ė Effective Dates ( ) Interim Limits (x) Final Limits

			BFFLU	EFFLUENT LIMITATIONS	TIONS	MONITORING	MONITORING REQUIREMENTS
PARAMETER & UNITS	BASIS FOR LIMITS	MULTIPLIER OR PRODUCTION	MONTHLY AVERAGE	MINIMUM	MAXIMUM	FREQUENCY	SAMPLE TYPE
Flow (MGD)	3	₹	NL	NA	NI	1/Day	Calculated
рн (S.U.)	ĸ		NA	0.9	0.6	2/Month	Calculated [d]
Total Residual Chlorine (mg/l) [a]	7		0.021	NA	0.026	2/Month	Calculated [d]
Total Phosphorus (mg/l)	ന		NA	NA	2.0	1/6 Months	Calculated [d]
Temperature $({}^{\circ}C)$	C)	-	NA	NA	[a]	1/Year	[9]
Heat Rejection (BTU/Hr)[c]	က		AN	NA	57.41 x 10(8)	Continuous	Recorded

NA = NOT APPLICABLE; NL = NO LIMIT, MONITORING REQUIREMENT ONLY

1/6 Months = In accordance with the following schedule: 1st half (January 1 - June 30); 2nd half (July 1 - December 31). 1/Year = Between January 1 and December 31.

Upon issuance of the permit, Discharge Monitoring Reports (DMRs) shall be submitted to the regional office at the frequency required by the permit regardless of whether an actual discharge occurs. In the event that there is no discharge for the monitoring period, then "no discharge" shall be reported on the DMR.

[a] See Parts I.B.15. and I.B.6. for quantification levels and reporting requirements, respectively.
[b] See Part I.B.15. for Thermal Mixing Zone requirements.
[c] See Part I.B.14. Heat rejection is the total heat rejected for outfalls 001 and 002 at the facility.
[d] Samples shall be collected at outfall 002 and shall be calculated for outfall 001 based on these samples.

The basis for the limitations codes are:
1. Technology (e.g., Federal Effluent Guidelines)
2. Water Quality Standards (9 VAC 25-260 et. seq.)
3. Best Professional Judgment

### (CONTINUED) - INDUSTRIAL EFFLUENT LIMITATIONS/MONITORING TABLE II

OUTFALL # 002

Sampling Point shall be downstream of the weir just prior to discharge under Waterview Road; internal outfalls 202, 203, 204, 205, and 111. Condenser cooling water - weir discharge. Outfall Description: 4911 SIC CODE:

Calculated Recorded SAMPLE TYPE Grab Grab Grab Grab Grab Grab Grab Q REQUIREMENTS MONITORING 1/6 Months Continuous 1/3 Months FREQUENCY Expiration 2/Month 2/Month 1/Year 1/Year 1/Year 1/Year 1/Day MAXIMUM To: 0.026 0 2.0 <u>a</u> N  $\overline{N}$ NI딛 NI Z EFFLUENT LIMITATIONS MIMINIM From: Issuance 0.9 NA NA NA NA NA NA MA NA NA AVERAGE MONTHLY 0.021 N NA NA NA ďΖ ΝĀ NA NA Ŋ Į Effective Dates MULTIPLIER PRODUCTION ( ) Interim Limits LIMITS BASIS FOR 14 14 14 ന ന  $\alpha$ ന Ò ന ന Chlorine Total Phosphorus (mg/1) Enterococci (n/cml) PARAMETER & UNITS Copper (x) Final Limits Temperature (°C) Total Residual Heat Rejection Zinc TSS (mg/l)[a] (BTU/Hr)[c] g Flow (MGD) Dissolved Dissolved PH (s.u.) (ug/l)[a] (ug/1)[a] (mg/1)

NA = NOT APPLICABLE; NL = NO LIMIT, MONITORING REQUIREMENT ONLY

<sup>1/3</sup> Months = In accordance with the following schedule: 1st quarter (January 1 - March 31); 2nd quarter (April 1 - June 30); 3rd quarter (July 1 September 30); 4th quarter (October 1 - December 31).

1/6 Months = In accordance with the following schedule: 1st half (January 1 - June 30); 2nd half (July 1 - December 31).

1/Year = Between January 1 and December 31.

Upon issuance of the permit, Discharge Monitoring Reports (DMRs) shall be submitted to the regional office at the frequency required by the permit regardless of whether an actual discharge occurs. In the event that there is no discharge for the monitoring period, then "no discharge" shall be reported on the DMR.

- [a] See Parts I.B.5. and I.B.6. for quantification levels and reporting requirements, respectively. [b] See Part I.B.15. for Thermal Mixing Zone requirements. [c] See Part I.B.14.

The basis for the limitations codes are:

- 1. Technology (e.g., Federal Effluent Guidelines)
  2. Water Quality Standards (9 VAC 25-260 et. seq.)
  3. Best Professional Judgment
  14. Best Professional Judgment for storm water discharges in the steam electric category (14)

# (CONTINUED) TABLE II - INDUSTRIAL EFFLUENT LIMITATIONS/MONITORING

OUTFALL #003 and 004

Outfall Description: Storm water from the ash landfill sediment ponds - 003 pond #1; 004 pond #2 (valved) 4911 SIC CODE:

PARAMETER & UNITS         BASIS FOR FOR LIMITS         MULTIPLIER PRODUCTION         EFFLUENT LIMITATIONS         MONITORING REQUIREMENTS           Flow (MGD)         3         MONITORING ORDINATION         NA         NL         1/Month         Estimate           PH         33         NA         6.0         9.0         1/Month         Grab           Total Suspended Solids         1         30         NA         100         1/Month         Grab           Oil & Grease         1         33         NA         20         1/Month         Grab           Total Phosphorus (mg/l)         3         NA         NA         2.0         1/Months         Grab	(x) Final Limits () Int	( ) Interim Limits	s Effective Dates -	From: I	Issuance	To: E	Expiration	
BASIS         MULTIPLIER         MONTHLY         MILMIN MAXIMUM         FREQUENCY           1         NIL         NA         NL         1/Month           1         1         1/Month         1/Month         1/Month           (mg/1)         3         NA         100         1/Month           (mg/1)         3         NA         100         1/Month				BEFLU	ENT LIMITAL	rions	MONITOI REQUIREN	RING
3       NL       NA       1/Month         1       NA       6.0       9.0       1/Month         1       30       NA       100       1/Month         1       15       NA       20       1/Month         3       NA       NA       2.0       1/6 Months	RAMETER & UNITS	BASIS FOR LIMITS	MULTIPLIER OR PRODUCTION	MONTHLY	MINIMUM	MAXIMUM	FREQUENCY	SAMPLE
3 NA 6.0 9.0 1/Month 1 30 NA 100 1/Month 1 15 NA 20 1/Month 3 NA NA 2.0 1/6 Months	Flow (MGD)	က		NL	NA	NL	1/Month	Estimate
1 15 NA 2.0 1/Month 3 NA 2.0 1/6 Months	Нd	m		ŊĄ	6.0	9.0	1/Month	Grab
1 15 NA 20 1/Month 3 NA 2.0 1/6 Months	Total Suspended Solids (mg/l)	1		30	AN	100	1/Month	Grab
3 NA NA 1/6 Months	Oil & Grease			15	NA	20	1/Month	Grab
	Total Phosphorus (mg/l)	m		NA	NA	2.0	1/6 Months	Grab

NA = NOT APPLICABLE; NL = NO LIMIT, MONITORING REQUIREMENT ONLY; I.S. = Immersion Stabilization

1st half (January 1 - June 30); 2nd half (July 1 - December 31), 1/6 Months = In accordance with the following schedule: Upon issuance of the permit, Discharge Monitoring Reports (DMRs) shall be submitted to the regional office at the frequency required by the permit regardless of whether an actual discharge occurs. In the event that there is no discharge for the monitoring period, then "no discharge" shall be reported on the DMR.

The basis for the limitations codes are:
1. Technology (e.g., Federal Effluent Guidelines)
2. Water Quality Standards (9 VAC 25-260 et. seg.)
3. Best Professional Judgment

OUTFALL # 005 and 006

Outfall Description: 005-Unit 1 condenser backwash; 006-Unit 2 condenser backwash SIC CODE: 4911

C		
ଚ		
-H		
ند		
To: Expiration		
ũ		
·d		
O.		
$\overline{\times}$		
函		
•		
Ο		
Ĕ	Control of the Contro	
-		
	21.00 10 10 10 10 10 10 10 10 10 10 10 10 1	
Φ		
Ü		
¤	Constitution of the consti	
Issuance	GAAT AND THE CONTRACT OF THE C	
$\Box$		
Ŋ		
Ø		
Н		
From:		
Ħ		
0		
Н		
Ξų		
1		
ective Dates		
Ψ		
+		
9		
FI		
a)		
7.6		
Ξ.		
7		
8		
Ē		
£Ε		
囚		
Ø		
Ţ		
Interim Limits		
띰		
-년		
H		
ا ہے		
Ħ		
ij		
4		
3		
Ţ		
IJ		
' '		
•		
-		
- 1		
Ø		
اند	11 (12 (12 (12 (12 (12 (12 (12 (12 (12 (	
-г-		
4		
.뭐		
انے		
ا ا		
Final Limits		
ď		
н		
щ		
ı		
$\neg$		
	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	

These outfalls shall contain backwash water from Unit 1 condenser (outfall 005) and the Unit 2 condenser (outfall 006) only. No process wastewater shall be discharged from these outfalls. No monitoring or reporting is required.

### - INDUSTRIAL EFFLUENT LIMITATIONS/MONITORING (CONTINUED) Ξ TABLE

dewatering; 202-outfall pumps pit sump; 203-outfall pumps pit sump backup; 204-outfall pumps cooling and seal OUTFALL # 007, 016, 017, 105, 202, 203 and 204
Outfall Description: 007-Intake pump(s) maintenance dewatering; 016-Intake pump(s) leak collection pit; 017hydrostatic relief system under the center pond of the ash landfill; 105-outfall pumps maintenance

SIC CODE:

		genera propinsi sila
	NAME OF THE PARTY	
	li santa	
		155 P. C.
	A SHOW	
	200000000000000000000000000000000000000	
_	(75 days)	
<u> </u>	Section 5	
0		
Expirat	destroites.	
'n.		
Ğ		Mark and the Miles of the Control of
	10000	
	erate interes	
24	2000	and the last of th
$\sim$		Annual County of the County of
[+]		
••		
Ω	6000	
<u> </u>	1004500-00	
۲.		
		The State Control of the State
		200.00000000000000000000000000000000000
/11		
Issuance		
Ŏ		
⊈		ran i reproduțiul de la
ന	n vantriini nadatavioni	
ij		Solitanation of
ัด		
íń		
رب لـــا		
, .		
	Shi cacay south	
=		
0		
Н		
From:	100000000000000000000000000000000000000	
E		4.5
•		15.55 (2010) 47.05 (11) (12)
70		and the second s
7.	green total	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
. ŭ		The state of the s
Ę.		
ate	7 (A)	
Date	A Section of the sect	
Date	A Committee of the Comm	
e Date		
ve Date		
ive Date	A STATE OF THE STA	
ive Date		
tive Date		
ctive Date		
ective Date		
fective Dates		
ய		
ய		
ய		
EF		
E E E		
E E E		
EF		
ய		
EF		
( ) Interim Limits Eff		
( ) Interim Limits Eff		
( ) Interim Limits Eff		
( ) Interim Limits Eff		
( ) Interim Limits Eff		
( ) Interim Limits Eff		
( ) Interim Limits Eff		
( ) Interim Limits Eff		
( ) Interim Limits Eff		
( ) Interim Limits Eff		
( ) Interim Limits Eff		
( ) Interim Limits Eff		
( ) Interim Limits Eff		
( ) Interim Limits Eff		
( ) Interim Limits Eff		
( ) Interim Limits Eff		
EF		
( ) Interim Limits Eff		
( ) Interim Limits Eff		

only. No process wastewater shall be discharged from these outfalls. No monitoring or reporting is required. These outfalls shall contain discharge from the dewatering of the intake pump(s)(007), intake pump(s) leak collection pit (016), hydrostatic relief system (017), outfall pumps maintenance dewatering (105), outfall pumps pit sump (202), outfall pumps pit sump backup (203), and outfall pumps cooling and seal water (204)

OUTFALL # 008 and 014

Outfall Description: Regulated storm water runoff from an industrial activity area; 008 - unit 3 area, ash handling areas; 014 - service road for intake cooling water pump

SIC CODE: 4911

	STORM		HARGE ATIONS		
PARAMETER & UNITS	REGS. 1-29* Or BPJ	MINIMUM	MUMIXAM	FREQUENCY	SAMPLE TYPE [c]
Flow (MG)	BPJ-14	NA	NL	1/3 Months	Estimate [b]
pH (s.u.)	BPJ-14	NL	NL NL	1/Year	Grab
TSS (mg/l) [d]	BPJ-14	NA	NL	1/Year	Grab
TPH (mg/l) [d]	BPJ	. NA	NL	1/Year	Grab
Total Phosphorus (mg/l)	BPJ	NA	2.0	1/Year	Grab
Dissolve Nickel (ug/l) [d][e]	BPJ	NA	NL	1/3 Months	Grab
Dissolve Copper (ug/l) [d][e]	BPJ	NA	NL	1/3 Months	Grab
Dissolve Zinc (ug/l) [d][e]	BPJ	NA	NL	1/3 Months	Grab

NA = NOT APPLICABLE; NL = NO LIMIT, MONITORING REQUIREMENT ONLY

1/3 Months = In accordance with the following schedule: 1st quarter (January 1 - March 31); 2nd quarter (April 1 - June 30); 3rd quarter (July 1 - September 30); 4th quarter (October 1 - December 31).

1/Year = Between January 1 and December 31.

Upon issuance of the permit, Discharge Monitoring Reports (DMRs) shall be submitted to the regional office at the frequency required by the permit regardless of whether an actual discharge occurs. In the event that there is no discharge for the monitoring period, then "no discharge" shall be reported on the DMR.

These outfalls are considered substantially identical; 008 may be sampled for 014; sample results shall be reported for both outfalls.

- [a] See Part I.D. (STORM WATER MANAGEMENT CONDITIONS) for additional storm water sampling and reporting requirements.
- [b] Estimate of the total volume of the discharge during the storm event.
- [c] The grab sample shall be taken within the first hour but not later than 24 hours of the discharge.
- [d] See Parts I.B.5. and I.B.6. for quantification levels and reporting requirements, respectively. TPH is the sum of individual gasoline range organics and diesel range organics or TPH-GRO and TPH-DRO to be measured by EPA SW 846 Method 8015C (2007) for gasoline and diesel range organics, or by EPA SW 846 Methods 8260B (1996) and 8270D (2007). If the combination of Methods 8260B and 8270D is used, the lab must report the total of gasoline range organics, diesel range organics and polynuclear aromatic hydrocarbons.

[e] See Part I.D. for Storm Water Evaluation requirements.

The bases for the limitations codes are:

Best Professional Judgment for storm water in category of steam electric facilities (14)

### (CONTINUED) - INDUSTRIAL EFFLUENT LIMITATIONS/MONITORING TABLE II

OUTFALL # 009, 013, 112 and 205 Outfall Description: Storm water outfalls not associated with a regulated industrial activity SIC CODE: 4911

- 1	
-	
-	
-	
1	
ద	
To: Expiration	
انت	
Ø	
뇐	
Ö.	
×	
ᆈ	
. 0	
∺	
	22 (12) (10) (10) (10) (10) (10) (10) (10) (10
	The state of the s
	The state of the s
4)	
ŏ	Control to the Contro
From: Issuance	
ις.	And the second s
ິນ.	
Ø	The state of the s
Н	
••	
Ĕ	
V.	
بعرا	
1	
ro.	
Φ	
ب	
ective Dates	
JI	
Φ	
>	ACT TO THE THE PARTY OF T
Ξ.	The course of th
ΰ	
4-1	
ĺτ	
Ø	
نه	And the second s
'n	
11	
H	man and man design and a second
⊭	
Ч	
Interim Limits	
Ċ	
1-1	
_	
)	
Ś	
nits	
٤	
٠Ц	
Н	
П	EARLINANIAN ARE CONTROL OF THE PROPERTY OF THE
ਕ	
2:	
inš	
Fină	
Final Limit	
K) Fina	

These outfalls shall contain only storm water not associated with a regulated industrial activity. There shall be no discharge of process wastewater from these outfalls. No monitoring or reporting is required.

# - STORM WATER EFFLUENT LIMITATIONS/MONITORING (CONTINUED) TABLE II

Outfall Description: Storm water outfalls associated with a regulated industrial activity OUTFALL # 106, 107, 108, 109, 110, 015 SIC CODE: 4911

d	
- Q	Service And Andrews Control of Co
<u>.</u>	
્ય	
Expiration	
Ω	23, 250, 100 per 250, 257, 251, 251, 251, 251, 251, 251, 251, 251
Ħ	
To: I	Branch and Carry Control (1994) Alban Control (1994
0	And the second s
F-4	
	Control of the contro
	A STATE OF THE STA
Φ	
Issuance	
Ğ	
S	
Ŋ	The state of the s
E	
From:	
伍	Control of the Contro
	The state of the s
1	
Ø	
T)	Service of the Control of the Contro
ğ	To plan to the state of the sta
∺	
Ď.	
ective Dates	The state of the s
ě	
Ε££	
되	
Interim Limits	Control of the second s
ij	<ul> <li>Leading to the control of the control</li></ul>
iπ	ENDERFORMSPRINGSRIANIA
ij	
Œ	
7.	
(e)	
h L	
_	
H	Parallel Committee of the Committee of t
I ()	
( ) I	
I ( )	
I () s	
()	
()	
imits ()	
imits ()	
imits ()	
imits ()	
imits ()	
imits ()	
()	

There shall be no discharge of process wastewater from these outfalls. No monitoring or reporting is required. These outfalls shall contain only storm water associated with a regulated industrial activity.

OUTFALL #010

Outfall Description: Regulated storm water runoff from industrial activity areas

- warehouse area SIC CODE: 4911

PARAMETER & UNITS	STORM		HARGE ATIONS		MONITORING REQUIREMENTS [a]	
	CATEGORY 1-29 or BPJ	MINIMUM	MAXIMUM	FREQUENCY	SAMPLE TYPE [c]	
Flow (MG)	BPJ-14	NA	NL	1/Year	Estimate [b]	
pH (S.U.)	BPJ-14	NL	NL	1/Year	Grab	
TSS (mg/l)[d]	BPJ-14	NA	NL	1/Year	Grab	
TPH (mg/l)[d]	ВРЈ	NA	NL	1/Year	Grab	
Dissolved Copper (ug/l) [d]	BPJ-14	NA	NL	1/Year	Grab	

1/Year = Between January 1 and December 31.

Upon issuance of the permit, Discharge Monitoring Reports (DMRs) shall be submitted to the regional office at the frequency required by the permit regardless of whether an actual discharge occurs. In the event that there is no discharge for the monitoring period, then "no discharge" shall be reported on the DMR.

- [a] See Part I.D. (STORM WATER MANAGEMENT CONDITIONS) for additional storm water sampling and reporting requirements.
- [b] Estimate of the total volume of the discharge during the storm event.
- [c] The grab sample shall be taken within the first hour but not later than 24 hours of the discharge.
- [d] See Parts I.B.5. and I.B.6. for quantification levels and reporting requirements, respectively.

TPH is the sum of individual gasoline range organics and diesel range organics or TPH-GRO and TPH-DRO to be measured by EPA SW 846 Method 8015C (2007) for gasoline and diesel range organics, or by EPA SW 846 Methods 8260B (1996) and 8270D (2007). If the combination of Methods 8260B and 8270D is used, the lab must report the total of gasoline range organics, diesel range organics and polynuclear aromatic hydrocarbons.

The basis for the limitations codes are:

Best Professional Judgment for storm water discharges in the steam electric category (14)

OUTFALL # 011 and 012

Outfall Description: regulated storm water runoff from industrial activity areas - switchyard, coal handling areas, maintenance, security and coal unloading buildings and access roads 011; area containing section of ash haul road 012 SIC CODE: 4911

PARAMETER & UNITS	STORM	DISCH LIMITA	HARGE ATIONS	MONIT REQUIREM	ORING ENTS [a]
	CATEGORY 1-29 or BPJ	MINIMUM	MAXIMUM	FREQUENCY	SAMPLE TYPE [c]
Flow (MG)	BPJ-14	NA	NL	1/Year	Estimate [b]
рН (S.U.)	BPJ-14	NL	NL	1/Year	Grab
TSS (mg/l)[d]	BPJ-14	NA	NL	1/Year	Grab
TPH (mg/l)[d]	BPJ	NA	NL	1/Year	Grab

NA = NOT APPLICABLE; NL = NO LIMIT, MONITORING REQUIREMENT ONLY

1/Year = Between January 1 and December 31.

Upon issuance of the permit, Discharge Monitoring Reports (DMRs) shall be submitted to the regional office at the frequency required by the permit regardless of whether an actual discharge occurs. In the event that there is no discharge for the monitoring period, then "no discharge" shall be reported on the DMR.

- [a] See Part I.D. (STORM WATER MANAGEMENT CONDITIONS) for additional storm water sampling and reporting requirements.
- [b] Estimate of the total volume of the discharge during the storm event.
- [c] The grab sample shall be taken within the first hour but not later than 24 hours of the discharge.
- [d] See Parts I.B.5. and I.B.6. for quantification levels and reporting requirements, respectively.

  TPH is the sum of individual gasoline range organics and diesel range organics or TPH-GRO and TPH-DRO to be
  measured by EPA SW 846 Method 8015C (2007) for gasoline and diesel range organics, or by EPA SW 846 Methods
  8260B (1996) and 8270D (2007). If the combination of Methods 8260B and 8270D is used, the lab must report the
  total of gasoline range organics, diesel range organics and polynuclear aromatic hydrocarbons.

The basis for the limitations codes are:

Best Professional Judgment for storm water discharges in the steam electric category (14)

# - INDUSTRIAL EFFLUENT LIMITATIONS/MONITORING (CONTINUED) TABLE II

OUTFALL #101

North and South Ash Finger Ponds Outfall Description:

SIC CODE: 4911

(x) Final Limits ( ) Int	( ) Interim Limits	ts Effective Dates -	From: Is:	Issuance 7	To: Expiration	cion	
			D H H H H	EFFLUENT LIMITATIONS	TIONS	MONITORING REQUIREMENTS	RING MENTS
PARAMETER & UNITS	BASIS FOR LIMITS	MULTIPLIER OR PRODUCTION	MONTHLY	MINIMUM	MAXIMUM	FREQUENCY	SAMPLE
Flow (MGD)	ю		Z	NA	IJN	1/Month	Estimate
Total Suspended Solids (mg/l)	<del>,</del>		30	AN	100	1/Month	Grab
Oil & Grease (mg/l)	г-1		15	NA	20	1/Month	Grab
Enterococci (n/cml)	Е		NA	NA	NE	1/Year	Grab

NA = NOT APPLICABLE; NL = NO LIMIT, MONITORING REQUIREMENT ONLY

1/Year = Between January 1 and December 31.

Upon issuance of the permit, Discharge Monitoring Reports (DMRs) shall be submitted to the regional office at the frequency required by the permit regardless of whether an actual discharge occurs. In the event that there is no discharge for the monitoring period, then "no discharge" shall be reported on the DMR.

The basis for the limitations codes are:
1. Technology (e.g., Federal Effluent Guidelines)
2. Water Quality Standards (9 VAC 25-260 et. seg.)
3. Best Professional Judgment

### (CONTINUED) - INDUSTRIAL EFFLUENT LIMITATIONS/MONITORING TABLE II

OUTFALL #102

Outfall Description: Metals cleaning basin

SIC CODE: 4911

Measured SAMPLE TYPE Grab Grab REQUIREMENTS [a] Grab Grab Grab Grab Grab Grab MONITORING FREQUENCY 1/Month 1/Month 1/Month 1/Month 1/Month 1/Month 1/Month 1/Month 1/Month Expiration MAXIMUM To: 1000 1000 100 584 117 NL 20 Q Ø EFFLUENT LIMITATIONS MINIMOM NA NA NA From: Issuance ΝĀ NA NA NA NA NA AVERAGE MONTHLY 1000 1000 175 N 30 15 88 Q Ø 1 Effective Dates MULTIPLIER PRODUCTION LIMITS BASIS FOR ( ) Interim Limits ന Suspended Solids (mg/1) Total Suspended Solids Grease (lbs/day) Copper (lbs/day) (lbs/day) & Grease (mg/l) Total Copper (ug/l) PARAMETER & UNITS Iron (ug/1) (x) Final Limits Iron Flow (MGD) (lbs/day) ζV Total Total Total Total Oil 011

Upon issuance of the permit, Discharge Monitoring Reports (DMRs) shall be submitted to the regional office at the frequency required by the permit regardless of whether an actual discharge occurs. In the event that there is no discharge for the monitoring period, then "no discharge" shall be reported on the DMR.

å [a] Unless otherwise approved, the sample shall be collected at the point where the recirculation line discharges into the line mixing basin. wastewater shall be added to the basin after the sample is collected prior to the discharge for the sample period.

NA = NOT APPLICABLE; NL = NO LIMIT; MONITORING REQUIREMENT ONLY

The basis for the limitations codes are:
1. Technology (e.g., Federal Effluent Guidelines)
2. Water Quality Standards (9 VAC 25-260 et. seq.)
3. Best Professional Judgment

OUTFALL #103

Outfall Description: Regulated storm water from coal pile runoff (valved)

SIC CODE: 4911

PARAMETER & UNITS	Basis For	DISCH LIMITA		MONITO REQUIRE	
	Limits	MINIMUM	MAXIMUM	FREQUENCY	SAMPLE TYPE
Flow (MGD)	3	NA	NL	1/6 Months	Estimate
TSS (mg/l) [a]	1	NA	50	1/6 Months	Grab
Dissolved Copper (ug/l) [b]	3	NA	NL	1/Year	Grab
Dissolved Nickel (ug/l) [b]	.3	NA	NL	1/Year	Grab
Dissolved Arsenic (ug/l) [b]	3	NA	NL	1/Year	Grab
Dissolved Zinc (ug/l) [b]	3	NA	NL	1/Year	Grab

NA = NOT APPLICABLE; NL = NO LIMIT, MONITORING REQUIREMENT ONLY

1/6 Months = In accordance with the following schedule: 1st half (January 1 - June 30); 2nd half (July 1 - December 31).

1/Year = Between January 1 and December 31.

Upon issuance of the permit, Discharge Monitoring Reports (DMRs) shall be submitted to the regional office at the frequency required by the permit regardless of whether an actual discharge occurs. In the event that there is no discharge for the monitoring period, then "no discharge" shall be reported on the DMR.

- [a] See Part I.B.12. for Overflow of Untreated Coal Pile Runoff from a 10-Year/24-Hour Storm.
- [b] See Parts [1.B.5. and I.B.6. for quantification levels and reporting requirements, respectively.

The basis for the limitations codes are:

- Technology (e.g., Federal Effluent Guidelines)
- 2. Water Quality Standards (9 VAC 25-260 et. seq.)
- 3. Best Professional Judgment

# (CONTINUED) TABLE II - INDUSTRIAL EFFLUENT LIMITATIONS/MONITORING

OUTFALL #104

Outfall Description: Coal Fly Ash Leachate Tank SIC CODE: 4911

(x) Final Limits ( ) Interim Limits Efi	Limits E	ffective Dates -	From: Issuance	suance	To: Ey	To: Expiration	
			DIJJE	EFFLUENT LIMITATIONS	SNOIJ	MONITORING REQUIREMENTS [a]	RING NTS [a]
PARAMETER & UNITS	BASIS FOR LIMITS	MULTIPLIER OR PRODUCTION	MONTHLY AVERAGE	MINIMOM	MUMIXAM	FREQUENCY	SAMELE
Flow (MGD)	m		NA	NA	NL	1/Month	Measured
Dissolved Copper (ug/1)[a]	٣		NA	NA	NE	1/Year	Grab
Dissolved Zinc (ug/l)[a]	က		NA	NA	NL	1/Year	Grab

NA = NOT APPLICABLE; NL = NO LIMIT, MONITORING REQUIREMENT ONLY

1/Year = Between January 1 and December 31.

Upon issuance of the permit, Discharge Monitoring Reports (DMRs) shall be submitted to the regional office at the frequency required by the permit regardless of whether an actual discharge occurs. In the event that there is no discharge for the monitoring period, then "no discharge" shall be reported on the DMR.

[a] See Parts I.B.5. and I.B.6. for quantification levels and reporting requirements, respectively.

The basis for the limitations codes are:
1. Technology (e.g., Federal Effluent Guidelines)
2. Water Quality Standards (9 VAC 25-260 et, seg.)
3. Best Professional Judgment

TABLE II - INDUSTRIAL EFFLUENT LIMITATIONS/MONITORING (CONTINUED)

OUTFALL # 111

Outfall Description: Intake Screen Wash

SIC CODE: 4911

اس	0302131014	
Ö		
ή.		
H B		
·ਰ.		
To: Expiration		
щ		
Ö		
Ħ		
41		
Issuance		
an		
ŭ		
Ň		g sgrade da 1814
- 1		
:: E		
From:		ğe (20. 27. 28. 29.)
됴		
1		
ທ		
ΘÜ		
ective Dates -		
(—)		ne vilolija kalasia
e G		
-:		
$\vec{\circ}$		
44		
[1]		The state of the s
1		
Interim Limits	Secret Bayes	
<u>٦</u>		TANK THE COURT OF THE STREET
i m		Advanced Appendix and prompts
П		
Ħ		
Γļ		
ţ.	(Šariya)	
Ľ	Andrews	
	And Andrews	
Ŋ		
ìt		
im		
Ä		
П		
пa		
Fina		
Fina		
X) Final Limits		

This outfall shall contain discharge from the washing of the intake screen(s). No other wastewater shall be discharged from these outfalls. No monitoring or reporting is required. See Part I.B.9. for additional requirements.